

LONDON MISSIONARY SOCIETY


(ESTABLISHED 1795)

LIVINGSTONE HOUSE, BROADWAY, WESTMINSTER, S.W.1

TELEPHONE:  
VICTORIA 5057 (3 LINES)

TELEGRAMS:  
"MISSIONARY SOWEST," LONDON

EDWARD DIAMOND, A.C.A.  
ASSISTANT TREASURER



2nd October, 1931.

The Secretary,  
Lloyds Register of Shipping,  
71, Fenchurch Street,  
E.C.

Dear Sir,

With reference to the sixty fathoms of cable recently shipped to Suva to be placed on Board the Auxiliary Schooner "John Williams V", registered number 161429, I beg to report that the cable has been inspected by Lloyds Surveyor and his Certificate is enclosed.

I understand that Lloyds Register has no Surveyor at any part which the vessel is likely to touch for some time to come, I should therefore be glad to know whether the attached report can be accepted as sufficient evidence for the purpose of Lloyds Register.

Yours faithfully,

Asst. Treasurer.



© 2019

Lloyd's Register  
Foundation

W1017 0044

Side Stringer, Angles..... 4 3 .30 3 1/2 x 3 x 30

Stiffeners, Spacing.....

Referred to the Chief ~~Ship~~ Surveyor.

*hks*

[3 OCT 1931

*Oliver*

Also for Mr. S. A. Hill to note.



© 2019

Lloyd's Register  
Foundation