

REGISTERED TONNAGE.
Under deck 186.43

Correction for Transverse Numeral—Rules, }
Sec. 13, Clauses 3 and 5..... }

+ 10%

Owner LONDON MIS

Residence LIVING

BROADWAY

ing to

le B
in 1

LAS

24
25
4
5

C O P Y

Auxiliary Screw Three Masted Schooner "JOHN WILLIAMS V"

This vessel was recently built by the Grangemouth

S U R V E Y R E P O R T .

Suva, Fiji,

26th August, 1931.

COPY.

Aux. Schooner "JOHN WILLIAMS V".

71, Fenchurch Street, E.C. 3.

This is to certify that I, Ernest W. G. Twentyman, the undersigned Marine Surveyor to Lloyd's Agents in Fiji, didm at the request of the Master, survey the four lengths of cable chain (60 fathoms) that has been imported for the use of the Aux. Schooner "John Williams V", and find that the chain is of the same dimensions as the cable now on board.


I have also sighted Board of Trade certificate No.46018, issued by Lloyd's Proving House, Cradley Heath, which has arrived with the chain in questionm, and find that same complies with the Board of Trade and Lloyd's requirements.

(Signed) Ernest W.G.Twentyman,

Marine Surveyor
to
Lloyd's Agents.

Fee for this survey and report: £1-1-0. (one guinea).

Yours faithfully



© 2019

Lloyd's Register
Foundation

21017-0048

Side Stringer, Angles..... 4 3 .30 3 1/2 x 3 x 30

Intercostal Plate

✓

Stiffeners, Spacing.....