

C O P Y

LLOYD'S REGISTER OF SHIPPING

Laxmi Building,  
Ballard Road,  
BOMBAY.

16th March, 1950 (Rec'd.20.3.50.)

Dear Sir,

S.S. "MAHARASHMI"

With further reference to your letter of the 30th December last, and to our letter of the 7th ultimo regarding the renewal of anchor chain cables on this vessel I beg to acquaint you that as yet there has been no opportunity for ranging the cables for examination.


Meanwhile the Owners are endeavouring to procure 135 fathoms of suitable second hand cable ex "IRRAWADI" or "KALMARSUND IX". These two vessels are being broken up at Bombay and their equipment letter is the same as that of the "MAHARASHMI".

Further advice in this connection will be forwarded at a later date.

I am, Dear Sir,

Yours faithfully,

Sgd: JOHN RUNDLE.



© 2019

W1017-0197

Lloyd's Register  
Foundation