

Dia. of Cylinders 82-31-52 Length of Stroke 36 Revs. per minute 100 Dia. of Screw shaft as per rule 11 1/2 screw shaft
Is the screw shaft fitted with a continuous liner the whole length of the stern tube yes Is the after end of the liner made not fit tightly

8mm. 4, 18.

Time of Receipt 4-53

TELEGRAM.

POST OFFICE TELEGRAPHS.

If the Receiver of an Inland Telegram doubts its accuracy he may have it repeated on payment of half the amount originally paid for its transmission, any fraction of 1d. less than 1d. being reckoned as 1d.; and if it be found that there was any inaccuracy, the amount paid for repetition will be refunded. Special conditions are applicable to the repetition of Foreign Telegrams.


Handed in at	Office of Origin and Service Instructions	Words	Charges to pay
	4/15 PM GLASGOW T	21	

Office Stamp.
FENCHURCH STREET
12 4
13 NO
ET.C

THIS FORM MUST ACCOMPANY ANY ENQUIRY RESPECTING THIS TELEGRAM. Received here at 4.43 P.M.

TO { COMMITTEE LDN =

33322 IRRAWADI BOILER APPROVED FIRST JANUARY AS
DUNSMUIR JACKSONS 422 SHOULD HAVE BEEN 442 PLAN
BEING FORWARDED TONIGHT = REGISTER +



© 2019

Lloyd's Register Foundation

Diameter at smallest part 7 1/4 Area supported by each stay 336 Working pressure by rules 209 Material of Front plates at bottom
Thickness 3/32 Material of Lower back plate S Thickness 6/16 Greatest pitch of stays 14 3/4 x 9 1/2 Working pressure of plate by
Mean pitch of stays 27/32

Referred to the Chief Ship Surveyor,
and the Chief Engineer Surveyor.

FROM

S. J. S. J.W.B.
13. 11. 13.



© 2019

Lloyd's Register
Foundation