

COPY.

Lloyd's Register of Shipping.

71, Fenchurch Street, E.C.3.

Your Ref:ER/NN.

3rd January, 1950.

Dear Sirs,

I beg to acknowledge the receipt of your letter of yesterday relative to the Steamer "ROANOKE", and to confirm the intimation given to your Representative this morning that in view of information having been received in November last that the vessel had been sold for breaking up purposes her class was withdrawn from the Register Book and a notation of "To be broken up" was inserted therein.

The vessel was submitted to the requirements of Special Survey (including the drilling of the shell plating) on the hull and machinery in April 1948 and the Boiler Survey was carried out in December of that year with the exception of the examination and adjustment of the safety valves.

Yours faithfully,

Clerk to the
Classification Committee.

Messrs. Radonicich Ltd.,
15, St. Helen's Place,
London, E.C.3.

P.S. The screwshaft was last drawn for inspection in
December, 1946.



© 2020

Lloyd's Register
Foundation