

Received by Chief Ship Surveyor 31. 1. 16

Received from Chief Ship Surveyor

SHIP'S NAME

Sheers Lethum

Rpt.

No. 1

No. 9209

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Particulars of Survey

1st Entry -

It is submitted that before this case receives consideration the Middleboro Surveyors should be requested to forward a detailed sketch showing how the floor plates are fitted to the channel fillers in the lower tween decks at the end of Nos 1, 2 & 3 hatchways.

31-1-16

Lr. 31. 1. 16.



© 2020

Lloyd's Register
Foundation

W1020-0158

Plans approved.

23.7.14.

Inches
Spacing in
Ship.

54

Inches
Ship, in Ship

20

1/2 62

46

1/2 46

8 62/44

64

46 40

46/36

1/2 P.P.

38 50/44

50/44

46 40

40/32

44

44

50/44

30