

Reference

new S.S. "Heitium" (Sir R. Dixon Esq
Is. No. 588)

Submitted the Middlesex Surveys
he informs that if ~~cargo~~ cargo battens are
not fitted in accordance with Section 42
par 5 a notation will be made in the
Register Book and on the certificate of
classification of the parts where they
are not fitted.

19.1.16
and 20.

App'd by the
Chairman

G. L. L. 16.
20.1.16

W1020-0162

carrying chilled meat.

The Owners Representatives state that they must have a

© 2020

Lloyd's Register
Foundation