

on the bearings in the stern tube, is the space charged with a plastic material insoluble in water and non-corrosive
are fitted, is the shaft lapped or protected between the liners

1/cp "Detrim"

Mdb. Rpt 9209.

Before this case receives the consideration of the Committee, it is submitted that, the Middlesbro' Surveyors should be requested to state how the turbines are grouped, viz, whether all the turbines are on one shaft, or whether they are divided on two shafts; if the latter they should state how they are arranged; as their report is not clear on this point.

Let:- 31/1/16

JWR



© 2020

Lloyd's Register
Foundation

W1020-0174

Heating Surface of Boilers 14710 ^{180/16} Is Forced Draft fitted yes No. and Description of Boilers Five S.E. to 360/16 Date of test 30.4.15 No. of Certifi