

Received by Chief Ship Surveyor 7. 1. 18

Received from Chief Ship Surveyor

VESSEL'S NAME Stl. Tw/S/S "PORT DARWIN". Rpt. Bel. No. 7894

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.


("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

As it now appears that the tonnage opening of this vessel is closed, the Belfast Surveyors should be requested to state whether cargo battens have been fitted in the shelter 'tween decks.

Lr Bel 7/1/18.

7. 1. 18



© 2020

W1021-0061 Lloyd's Register
Foundation