

B. 5m.1.36.

FREEBOARD REPORT on the*"Barnes"**Mr Parsons.*

The registered depth reported on the Blue Form is incorrect. The Board of Trade (Tonnage Department) are taking action to issue a new Certificate of Registry with the correct depth inserted viz:- 12.75 feet and not 16 feet 6.5 inches as stated on the Blue Form.

The above information was obtained by telephone this morning.

W1024-0130

Lloyd's Register  
Foundation