

to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME Steel Screw M.S. "CAMEO"

Report

Gls.

No. 58006

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Date of Survey

FIRST ENTRY

When due

--

*100A1

1 Dk.


Cell. DB 129' 206t, FPT 88t, APT 37t.

FK, 3 BH, Cem., Lloyd's A & CP.

P 53', Q 79', F 28'

Machy aft.

The Glasgow Office ^{length} should be requested
to forward the ~~overall~~ length in accordance
with Circular 1703. = 210'-10"



© 2021

Lloyd's Register
Foundation

W1024-0133