

W1025 - 0192 1/2

E.E.

Lloyd's Register of British & Foreign Shipping,

97 & 98, Scottish Provident Buildings,
Donegall Square, West,

Belfast, 17th August 1915.

LLOYDS REGISTER
LONDON

REC'D AUG 18 315
AN80 18

Secretary.

Reverting to my First Entry Report No. 7558 on H.M.S. "ORBITA",
I have to note that it is not proposed to furnish a Report on the Electric
Lighting Installation of the vessel, until her services as an Auxil-
iary Cruiser are no longer required, and the vessel is completed as a
passenger vessel.


At present, only a very small portion of the Electric Light is
erected, for temporary purposes.

I am, Sir,

Your Obedient Servant,

R. F. Beveridge

DATE OF BUILD 4.15



© 2020

W1025 - 0191

Lloyd's Register
Foundation

Spacing	30 1/2	30 1/2	Angles on ditto	3 1/2 x 3 1/2
BEAMS, Peep Deck, Angle, Bulb Angle, Plate,			Tie Plates	3 1/2 x 3 1/2
Toe Bulb or Channel			Deck. Material and thickness	Steel 30
Angles on upper edge			SHADE	Deck Stringer Plate, bulb & thickness

Referred to the Chief Engineer Surveyor.

Aug 18 1915

ARRK

Submitted the record
of "Elec Light" may
be posted

ARRK

23.8.15

ASTORIA 2300 L
NOV 10 1915
CIC 21 200 203A
98MA

© 2020

SEE'S NAME See

he remarks of the Chi

("The enforcement to
to bring out clear
presented in the en

Lloyd's Register
Foundation

ted by Chief Ship Survey

Transverse No.

Framing: Table

Longitudinal N

Deck Sheerstra

Flat plate keel

Equivalent str

(See Sepa

This ves

ules and the a

e classed

recommended. T

o top of statu

essel's sides,

ecorded in the

s shown on the

ertificate of

100 A.1. ("Sta

2 Dks (Sel) 8

W.B = Cell DB

FK & BK 2",

DATE

"Spacing ...
The Ball of Glass
Angles on type edge
Spacing ...