

MR. MILLAR.

m.v. "UDDU" ex M.M.S. 1013

This wood motor minesweeper was built to standard design under the supervision of the Society's Surveyors, but was not classed owing to unseasoned timbers being used in the construction. It is suggested that as vessels of this type have already been classed with the Society the Oslo Surveyors should be assisted by sending them a copy of the First Entry of a similar case made out in pencil, so that the Surveyors might verify the scantlings and arrangements and at the same time make any amendments which may be necessary to suit No. 1013.

  
26th July, 1948.



© 2020

Lloyd's Register  
Foundation

w1026-0163