

Space  
Crown of  
Room

110-49

Proportions—Depths to Length—Upper Deck Beam at 13.20

(Where necessary to  
evidence

W1028-0022

& FULTON, LTD.  
SHIP OWNERS  
INSURANCE BROKERS.

1 CATHCART STREET,

ADDRESS, "ELF, GREENOCK"  
TELEPHONE NO 726.  
METHODS USED  
STANDARDS, STANDARD AND WATKINS.

GREENOCK 1st December 1914.

The Secretary

Lloyd's Register of British & Foreign Shipping,  
LONDON. E.C.

Sr,


In connection with a steamer we have contracted for with  
Hamilton & Co. Ltd, Port Glasgow, we desire that the Bulkhead  
between deck hold be omitted in order to suit the requirements of  
the, and trust you will meet our wishes in this matter.

The Yard Number is "307."

We are


Yours faithfully

Lang & Fulton, Ltd,



Director.

LOYDS' REGISTER,  
GREENOCK,  
Recd. 5. DEC. 1914



© 2020

Lloyd's Register  
Foundation

Spacing ..... Longitudinal framing ..... Angles on ditto, No. ....  
Second Deck Single A. L. B. .... Tie Plates outside H. ....