

Wing Lakeland

Lloyd's Register of Shipping.

(Reconnu par la Loi Belge sur la sécurité des Navires.)
(Arrêté Ministériel du 8 Janvier, 1921.)



LLOYD'S REGISTER

Recd. 1 MAY. 1925

Ansd.

LONDON

Maritime Buildings,
Quai Tavernier, 4,
Antwerp, 29th April 1925.

All communications to be addressed to
THE SURVEYORS.

S. Sir,

With regard to the case of the S/S "JORDAENS", Antwerp Report No.13631 referred to in Classing Letter of the 28th instant, we have to inform you that the weather decks were tested as required by the Rules and this fact is mentioned in the appointed place on the report. The bulkheads & tunnel have also been tested as required by the Rules and found satisfactory.

The freeboard has been verified and cut in on the vessel's sides as reported on our Freeboard Verification Form No.13606 forwarded to you on the 8th instant, upon receipt of which you forwarded us the Freeboard Certificates.

We are, Sir,

Yours faithfully,

The Surveyors,

per:-

The Secretary,

LONDON.



© 2020

Lloyd's Register
Foundation

on the vessels sides but the surveyors should be requested to make if this

W1029-0139

F
10. 130
Commit
ISO
DTA
D
P
16.
P/ 27.4.25
bear
ed
if this

Referred to the Chief Ship Surveyor.

C.S.S.

-1 MAY 1925

Also for Mr. S. A. Hill to note

W. S. 25

[Handwritten scribbles]

mirrored bleed-through text from the reverse side of the page, including the words "LLOYD'S REGISTER" and "VESSEL'S".



© 2020 Lloyd's Register Foundation

Received by C
VESSEL'S

19. Km
Frans

Frami

Longi

Rules
be cla