

LLOYD'S REGISTER OF SHIPPING

PORT of Hong Kong

13th February 1939.

THIS IS TO CERTIFY that

C. ROWCLIFFE

the undersigned Surveyor to this Society did at the request of The Taikoo Dockyard & Engineering Co. of Hong Kong Ltd. attend at Taikoo Docks on the 7th. February 1939 and subsequently in order to examine and test two rolled steel tail shafts rough turned 6" diameter x 27'-0" approx. and two open hearth steel forgings of extension shafts, rough turned 6" diameter with couplings 12" and 16" diameter respectively at either end, made to the order of Messrs. The De La Rama S.S.Co. Inc. Manila.

These shafts were examined in a black and rough machined condition and found to be as far as could be ascertained sound and free from defects.

RESULTS OF TESTS

	Tensile Test Tons per "	Extension per cent in 3"	Bend Test
Tail Shaft No.372	31.4 tons	35%	180° without fracture
" " No.373	31.4 "	34%	180°
Extension Shaft No.374	31.2 "	33%	180°
" " No.375	31.2 "	33%	180°

IDENTIFICATION MARKS

Tail Shaft	Tail Shaft	Extension Shafts
LLOYDS	LLOYDS	LLOYDS LLOYDS
No.372	No.373	No.374 No.375
CRR.11-2-39	CRR.11-2-39	CRR.11-2-39 CRR.11-2-39

(Sgd.) Chas. R. ROWCLIFFE
Surveyor to Lloyd's Register



© 2021

Lloyd's Register
Foundation

W103-0020