

10,451.

No. _____ Place Hong Kong

We request that the Comm
he Society's Surveyors to Specially S
Engines and Boilers of the Vessel No. W. S. Bailey & Co^{rs} for Messrs.

of _____ Tons. Length 135'-0" sp.

intended to be Classed A.1. Manufact

We undertake to arrange full,
urveyors to carry out the duty in qu
r the Surveyors' services, in addition
penses incurred by the Surveyors in

This request is made upon the
f Lloyd's Register of Shipping, which

While the Committee use their best endeavours to ensure th
understood that neither the Committee nor the Society are under any
in any report or certificate issued by the Society or its Surveyors,
Society, or for any error of judgment, default, or negligence of the S

W.S. Bailey
15/1/25

Engine Makers Campbell
Boiler Makers Yarrow

Signature

To the Secretary,

Lloyd's Register of Shipping

71, Fenchurch

W103-0165(1/2)

For W. S. BAILEY

12. 1. 25.

(Received at London Office..... 19..)

Date 4th Oct / Sept 1924

Committee of Lloyd's Register will instruct survey during Construction the Hull, 233 building by Messrs.

Yanco Co Manila Breadth 27'-6" , Depth 8'-3"

Manila Bay

For every facility to be given to the vessel, and we agree to pay the fees in to the actual travelling and other connexion therewith.

On the terms of the Rules and Regulations provide that:-

For the functions of the Society are properly executed, it is to be held responsible for any inaccuracy in any entry in the Register Book or other publication of the Surveyors, or other Officers or Agents of the Society.

Calderwood 1034 Paisley ? Co Glasgow 1507

For W. S. BAILEY & Co., Ltd.

Manray

asst. Managing Director

Street, London. E.C. (3)

W103-165 (2/2)

Lloyd's Register Foundation