

SURVEY OF SHIP.

Lloyd's
H/OVH1

I, **William Guy Robertson,** certify
that at the request of Messrs. Peirce Leslie & Co., Ltd.,
Lloyd's Agents at Mangalore, I surveyed the s.s. "Marina" on the
6th day of April 1949 in consequence of her having
reported a hole
in ship side plating in No. 5 Hatch.

On examination of this vessel on the day named I found
that
said hole had been blanked off with plate joint & two bolts
securing to ship's side. Over this a cement box had been
positioned and having been put there over 36 hr. previously,
had completely set.

From the survey that I have been able to make, as far as
possible, I conscientiously believe the said vessel can proceed on
her voyage.-

W. G. Robertson.

(Signature of Surveyor)


Dated at

Mangalore, 6th April 1949

Chief Engineer S. S. Shajahan

Copy to:-

The Controller of Agencies,
Lloyds,
London E.C.3.



© 2020

Lloyd's Register
Foundation