

URGENT.

TELEPHONE NO. 50415 & 52909.  
50615 & 52209.

PUMPING ARRANGEMENT Endorsement.

M.V. "Francois Jixier"  
Shipbuilders: Messrs. ~~M.V. TRIER~~ Yard No.  
Engineers: Messrs. ~~S.S. LITTLE & CO~~ (N° 80087 R.C.) Engine No.  
Owners: Messrs.

It is submitted that the plan of oil fuel piping  
~~Pumping Arrangement~~ for the donkey boiler  
merits approval, provided the arrangements be as  
shown and amended on the plan and the remaining  
requirements of Section 20 ~~and 24~~ of the Rules (1934-5)  
be complied with so far as they are applicable.

It is noted that only one feed water tank is  
fitted and that oil fuel for the boiler will be injected  
by steam and in the circumstances the Surveyors  
should ascertain that the amount of feed water  
carried is adequate for the service on which the  
vessel will be engaged.

The Surveyors should be reminded  
that an amended plan of bilge and ballast  
pumping arrangement is awaited.

W.G.A.  
12/3/35.

Return plan.

Retain copy.

L 12/3/35

E. 4. 5c.1.35. T.



© 2020

Lloyd's Register  
Foundation

W103170022

state in which tanks oil fuel will be carried.

13-3-35