

COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C. 3.

15th December, 1919.

Dear Sirs,

With reference to your First Entry Report, No. 41734, on the Steel Screw Steamer "UALAN", I should be obliged if you will forward a sketch of Rudder shewing the position of arms.

Will you also please state whether the thickness of keel is as per plan, or as given on report. The thicknesses of shell plating at ends of vessel should also be given, and you should state whether the sheerstrake is doubled or increased in thickness in way of Poop Front.

I am, Dear Sirs,

Yours faithfully,

Secretary.

The Surveyors,
CARDIFF.

No. 417

ing Committ

nd also
points

he Survey
ition of
s of Keel
Rating at
her the

5-12-19



© 2020

Lloyd's Register
Foundation

Angles on upper edge							
Spacing							
Top Deck, Angle, Bulb Angle, Plate, } Tee Bulb, or Channel	5 1/2	2 7/8	35				
Angles on upper edge							
Plating							
Deck. Mat							
Bridg							
Suit of							
Size, Shrou							