

for issue to the Owners' Representatives, Messrs.
J.R. Douglas, Frangos & Co., Ltd., London.

We also enclose copy of each report for your
record purposes.

COPY.

It will be noted from the second damage report,
that this damage was caused by the vessel's
damage to the hull.

Lloyd's Register of Shipping,

We are, 71, Fenchurch Street, E.C.3.

11th May, 1950.

ENCLOSURES

Dear Sirs,

With reference to your letter of the 24th and my acknowledgement of the 26th ultimo respecting the Steamer "CYGNET", I now have pleasure in enclosing herewith two damage reports (in duplicate) which have now been received from the Society's Surveyors at Grimsby.

Yours faithfully,

Clerk to the
Classification Committee.

Messrs. J.R. Douglas, Frangos & Co. Ltd.,
1, Fenchurch Buildings,
Fenchurch Street,
London, E.C.3.

Lloyd's Register
Foundation

W1031-0339

rudder
tackle

the

Other

Copy

Whe

Boat

Mast

Cond

Equi

Anch

Cable

"

"

Chain

Haws

Stand

Sails

vessel in the
"to remain