

POSTPONED SURVEYS.

Case of the..... S.S. "ACCRINGTON".....

No. 50157. in Reg. Bk. tons, Built.....

Classed..... Owners.....

Port of Registry.....

Survey Due..... Special Survey due 7,50. Part held on machinery.
Load Line Certificate expired 31,12,50.
Defective plain and stay tubes and front end
plates in port and starboard boilers, also defective
wrapper plate in centre box of starboard boiler
to be specially examined and repaired before the
end of 12,50. (8 mos. limit)

In reply to enquiry the Ipswich Surveyor states that this vessel
is laid up at Harwich and that the Executive of the British Railways
is expected to decide some time this month whether the vessel is to
be kept in service or offered for sale.

Committee's Minute..... FRI. 2 FEB 1951.....

Decision..... Deferred.....

subject

