

COPY.

# Lloyd's Register of Shipping.



Port LONDON.

12th May, 1950.

This is to Certify that I have

Surveyed the S.S. "INDIAN ENTERPRISE", 7519 tons gross of London,

as she lay in Tilbury Dock on the 10th May, 1950, on account of

damage stated to have been sustained by contact with lock entrance  
when vessel was leaving Sandon Dock, Liverpool, for London, in the  
partly loaded condition on the 6th May, 1950,

and that I have transmitted to the Committee of Lloyd's

Register of Shipping, London, a Report, stating that all repairs

recommended by me have been completed to my satisfaction, and

that I have Recommended that she be continued as classed

without record of docking, subject to indented bulwark and

sheer stroke plates, etc. (P.S.A.) abreast No. 5 Hold being

dealt with at next dry docking,

being fit to carry dry and perishable cargoes.

Fee: - 5l. 4s. 0.

Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—  
The Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed,  
and it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be  
held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register  
other than the publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member  
of the Surveyors, or other Officers or Agents of the Society.

