

ed by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

EL'S NAME "CASSIAR"

REPORT Ver No. 7365

emarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

General Examination became due 9,47.


The vessels class is subject to a bower anchor and 15 fathoms of chain cable being supplied.

The VANCOUVER Surveyors report 8,47 vessel examined afloat and requirements of a General Examination complied with. On account of wear and tear, all main hatchway covers were renewed.

A bower anchor and 15 fathoms of chain cable (as above) ~~were~~, placed on board and marks of same verified with certificates.

IT IS SUBMITTED the vessel is eligible to remain as classed with record of "Examined 8,47" as recommended, without special condition.

"Examined 8,47 Ver".



3.10.47.

© 2020

Lloyd's Register  
Foundation

W1038-0216