

3m, 11.30.

3 - APR 1940

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

"ALBERTO TREVES"

Rpt. Gen.

No. 16177

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The class is subject to indented keel plate No. 5 and shell plate B.5 (s.s.) being dealt with at the first favourable opportunity.

The 2nd Special Survey No. 2 due 9.39 has been commenced.

Permanent repairs are required to the aftermost keel plate at the first favourable opportunity.

Repairs are also required to tank side brackets in Nos. 4 and 5 holds, to watertight bulkhead between Nos. 4 and 5 holds in way of port and starboard bilges and to watertight floor aft of No. 6 double bottom tank (port and starboard).

The Genoa Surveyors now report the vessel afloat and the Special Survey advanced and minor repairs effected.

It is stated the Special Survey will be advanced and if possible completed on the vessel's return to Genoa or Trieste in about 3 months' time.

It is submitted action be deferred.

Handwritten signature and date: 29.4.40



© 2020

Lloyd's Register
Foundation

11041-0087