

Quastasia

Rot-1996.

It is concluded that that all the requirements of Sec. 14 of the Rules for electric fittings have been complied with but this should be confirmed by the Surveyor.

He should also state whether the lengths of cable in the forward accommodation & deck portables are correctly reported as these lengths would give a drop of pressure considerably in excess of that allowed by the Rules.

Classified to Rot:- 30/1/34

27/4/37

Lloyd's Register
Foundation

W1043-0083

bars

, individual fuses to voltmeter, pilot or earth lamp

, connections of switch

Main Switchgear description of switchgear for each generator and each outgoing circuit, and arrangement of equalizer switches