

Rpt. 8.

(Received at London Office)

No. 111276A

# REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report... When handed in at Local Office... 19... Port of London

No. in Reg. Book. 05547 Survey held at on the Wood, Iron or Steel 8.8" BOIS ROSE Date, First Survey... Last Survey... 1- 19 44

TONNAGE :- Built at Aberdeen By whom Hall, Russell & Co. Ltd. When 1940 3  
GROSS 1374 Owners L.A. des Pêcheries de Fecamp Owners' Address...  
UNDER DK 1122 Managers... Port belonging to Fecamp  
NET 837

Surveyed Afloat or in Dry Dock? Name of Dock... Destined Voyage...

Cell DBor DBa... feet; uE & B... feet; f... feet }  
total capacity... tons. FPT... tons; APT... tons; MT... feet... tons. }

N.B. All alterations in the existing records should be underlined.

Last Report, No. 10228 Port Msl.

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined.

Was a damage report made by anyone else? if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)	
CHARACTER * for Special Survey Date of last Survey and of Periodical Surveys	Machinery and Boiler Surveys (Including date of N.B., if any).
<u>T10071</u>	<u>TLMC 3.40</u>
<u>Steam Trawler</u>	<u>TS CL</u>
<u>10.41</u>	
<u>filled fuel 3.40, F.P. above 150°F.</u>	
<b>SURVEYS DELAYED.</b>	
Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.	

If so, is the Report sent now, or when will it be sent?

SUMMARY OF DAMAGE REPAIRS :-	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items :-
Renewed ...								
Removed and Faired or Repaired								
Faired or Repaired in place ...								

PRESENT CONDITION OF THE			
Decks	Bulkheads	Engine Room Skylights	Copper, or Y.M. (State if on Felt.)
Caulking of Decks	Ceiling	Coal Bunkers, Openings, Covers, &c.	When fitted, Month Year
Coamings	Cement or Asphalt	Oil Bunkers	Boats
Beams & Fastenings	Rudder	Scuppers	Masts, Yards, &c.
Outside Plating	Steering gear and its connections	Cargo Hatchways	Condition, how ascertained (State if wedges removed.)
" " In way of sidelights	Windlass	Hatches	Equipment letter
Frames	Have pumps been examined and found efficient?	Planking	Anchors, No. of
Reverse Frames	Have Sluice Valves been examined and found efficient?	Caulking	Cables (State if now ranged)
Longitudinals	Have Watertight Doors been examined and found efficient?	Treenails	" length (on board.) mean diamr.
Transverses	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson	" Rule length size
Floors	Air and Sounding Pipes	Transoms, Pointers & Crutches	Chain Locker
Keelsons	Doubling Plates under Sounding Pipes	Timbers of Frame at openings	Hawsers & Warps
Stringers		" " at other places	Standing and Running Rigging
Inner Bottom Plating		Stringers, Clamps & Shelves	Sails
Have the Tanks been examined internally?		Salting (State if examined.)	
Have the Tanks been tested?			

General Observations, Opinion as to Class, Recommendation, &c. :-  
State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

Survey Fee (per Sect. on 29)	£	:	:	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 29)	£	:	:	19.
Travelling Expenses (if chargeable)	£	:	:	Received by me,
Second Surveyor's Fee (if any)	£	:	:	19.

Committee's Minute... Character Assigned OMIT CLASS ON RE-PRINT.

TUES. 25 JAN 1944

RETAIN

© 2020  
Surveyor to Lloyd's Register of Shipping.  
Lloyd's Register Foundation  
W1044-0003

Is Certificate required? If so, to be sent to

10m 9/145.—Transfer Ink. (MADE AND PRINTED IN ENGLAND.) (The Surveys are required not to write on or below the space for Committee's Minute.)

