

Received by Chief Ship Surveyor 16.3.17

Received from Chief Ship Surveyor \_\_\_\_\_

VESSEL'S NAME Sheless Moravia

Rpt. Inl

No. 29849

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 35-95

Depth "d" 11.75

Framing: Table No. 3. page 9

Description Single angle as approved

Longitudinal No. 4673

Proportions  $\frac{\text{Length}}{\text{Depth}} = 9.9$

~~Deck~~ Sheerstrake - 62 of an inch instead of 36 as reqd.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed ❖ 100 A.1. (Steel) Steam Trawler, as recommended

❖ 100 A.1. Steel, Steam Trawler

1.5K.

BK. 8" 4BH. Lem. Lloyd's area. Q 72

M  
16.3.17



© 2019

Lloyd's Register Foundation  
W105-0050