

71, Fenchurch Street, E.C.3.

CRANBROOK SHIPPING COMPANY LTD.
SHIP OWNERS AND FREIGHT CONTRACTORS

TELEPHONE: AVENUE 1836.
TELEGRAMS: DAVIETIM-ALD, LONDON,
DIRECTORS:

P. RUBIN (BRITISH, POLISH ORIGIN)
L. F. MILTON.

*Bevis Marks House,
Bevis Marks,*

London, 18th January 1946
E.C.3.

Your ref: R.

The Secretary,
Lloyd's Register of Shipping,
71, Fenchurch Street,
E.C.3

RECEIVED
19 JAN 1946
ick 2/1
ANSD


Dear Sir,

S/T "ILFRACOMBE"

In reply to your letter of the 15th instant. The position in regard to the above vessel is that she was severely damaged as a result of stranding off Kilronan. She was eventually salvaged and taken to Galway where, after further examination, it was arranged between Underwriters and ourselves that the vessel should be regarded as a Constructive Total Loss. The vessel now belongs to Underwriters and if you require any further information as to her condition, we would suggest that you communicate with the Salvage Association.

Yours faithfully,

CRANBROOK SHIPPING CO LTD



DIRECTOR

Lloyd's Register
Foundation

BEVIS MARKS HOUSE,
Bevis Marks,
E.C. 3.

Referred to Mr. Spray.

[Handwritten signature]

[Handwritten signature]



© 2020

Lloyd's Register
Foundation

BE LOW WATER. THE MARINE
external damage on port or starboard
sides but some water was below floor-
ing of hold nearest fore-castle, and below

except amiships. where about 10 ft. is
on the ground. Port side is visible
from stem to stern and the keel, part of