

FEES... 1768.05
Room 604.34
on Snaces 28.98

2nd Number 18,694
Proportions—Breathths to Length 6.7

Managers (Where necessary to be entered in Reg. Bo)
Residence

W1054-0210

Lloyd's Register of British and Foreign Shipping.

REC'D 13 JUL 1901
ANS'D 18 Julth

56, John Street, Sunderland.
17th July 1901

The Secretary
London
Sir

I beg to inform you, that in the anchor equipment supplied to Messrs The Strand Shipway Co. Ltd. S.S. "Sratia" yard No 105, the second bower anchor has come out 14 lbs light, and the other anchors being according to rule the total weight is deficient by that amount. The rule weight of the anchor in question is 34. 2. 0 and actual weight as per certificate 34. 1. 14.

The matter is respectfully submitted for the consideration of the Committee

I am, Sir

Your obedient servant

J. Allan



Lloyd's Register
Foundation

average space.....	Centre-line BHD fore & aft hold	Centre-line bulkhead	" Angle on ditto.....
In 'tween Decks, Size and Spacing	" "	" "	" Tie Plates
" Hold " "	" "	" "	" Deck, Material and thickness IRON
Quarter, 'tween Dks., " "	" "	" "	Forecastle Deck Stringer Plate, brdth & thcknss
" in Hold " "	" "	" "	" Angle on ditto.....

Referred to the Chief Ship Surveyor.

gfd

18 JUL 1901

C. X. J.
18/7/01



© 2020

Lloyd's Register
Foundation