

1

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME Stl S "TOMISLAV" Report SK No. 18965**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR:**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/82.)

Nature of Survey 1st Entry When due Revised Rule Rule

✠ 100 A. I. (Steel)

2 D^{ko} (Stl)

Cell D.B. 342' 1050t, D.T. a 35' 965t, A.P.T. 205t

F.K, "Intermediate Turn D^{ko} B.H in after hold dispensed with""5 B.H to upper D^{ko} 1 B.H to 2nd D^{ko}", pt Cem, Plyds ARCP
P 38', B 133', F 37'.

© 2020

12.10.28.

Lloyd's Register
Foundation

W1061-0195