

F.E.

3571

mittee.

Motor Trawlers "PORT LEVEN" & "PORT NATAL"

The machinery of these vessels was not complete when they left Lisbon, and arrangements were made for the additional items to be supplied and fitted on the vessels' arrival in the U.K. A special condition was accordingly placed in the vessels' class.

The vessels have now been taken over by the Admiralty and the Hull Surveyors have forwarded a letter from the Admiralty in which it is stated that the outstanding items have been dealt with.

It is submitted that these vessels are eligible to remain as CLASSED without special conditions.

The Nottingham Surveyors should be informed that according to a letter received from the Admiralty an additional air receiver for each vessel was ordered from Messrs. Ruston & Hornsby Ltd. and fitted on arrival of the two vessels in the U.K. They should be requested to state if these additional air receivers were constructed under special survey, and if so, to forward a copy of the certificate. The receivers originally intended for these vessels were covered by Nottingham certificates Nos. C.580, 581, 771 and 772.

.....  
31.3.43



© 2019

W1065-0107 Register  
W1065-0115  
W1065-0115

Side Keelsons, No. each side.....

08

thickness of Intercostal Plate...

0.28

0.30

Spacing.....