

MEMORANDUM

From : LLOYD'S REGISTER OF SHIPPING, HIGH CLOSE, WOKINGHAM.

(Ref. H.)

To The Surveyor(s) at HULL.

Date: 18th September, 1945.

Vessel's Name: Motor Trawler "PORTAFERRY".

Question: I shall be glad if you will ascertain from the Owners and let me know what arrangements are proposed to be made to carry out the Modified Survey of the Oil Engines, which became due at the end of June last.

Answer:

Date: 26th Sept. 1945.

This vessel is being operated by the Government. The Loch Fishing Co of Hull, Ltd., have no knowledge of her whereabouts and are unable to give any information concerning survey requirements.

Inner Bottom Plating.....
Have the Tanks been examined internally ?.....
Have the Tanks been tested ?.....

examined and found efficient ?.....
Air and Sounding Pipes.....
Doubling Plates under Sounding Pipes.....

" " at other places.....
Stringers, Clamps & Shelves.....
Salting.....
(State if examined.)

General Observations, Opinion as to Class, Recommendation, &c. :—

er Items :—

Copper, or Y.M....
(State if on F....
When fitted, Mo

Boats

Masts, Yards, &c

Condition, how a
(State if wedg

Equipment letter

Anchor, No. of

Cables (State if n

" length.....

(on b

" Rule lengt

Chain Locker.....

Hawsers & Warp


Standing and Run

Sails.....

© 2019

W1065-0134

Lloyd's Register Foundation

[illegible]

МУНИЦИПАЛЬНОМУ

U.S. REGISTER OF SHIPPING, HIGH SEAS.

1109

2

© 2019
Lloyd's Register
Foundation

If so, is the Report sent

SUMMARY OF

Renewed

Removed

Paired or

PRESENT CONT

Decks

Caulking or Dec

Coatings

Beams & Kasten

Outside Playing...

” ” I

Times

Reverse Frames...

Longitudinal

Transverses

Neelsons

..... **svægm.**

Inner Bottom Plate

have the 180Ks

have the tanks

Minutes.)

General