

copy 19

Department of Transport, Canada

Steamship Inspector's Office

AS

At..... Vancouver, B. C.....

..... 13th December, 1937.....

RECEIVED
DEC 14 1937

Mr. A. Scott,
Lloyd's Surveyor,
1519 Marine Building,
Vancouver, B.C.

Dear Sir:

S.S. "CHELOHSIN"

I beg to advise you that while the above named steamer was hauled out on the slipway at the B. C. Marine on 15th January 1937, both tailshafts (continuous liners) were drawn inboard, examined and found good. The after bearing on the starboard shaft was re-wooded and the shafts replaced in good order.

Yours truly,

James Brydon
Steamship Inspector.



© 2020

Lloyd's Register
Foundation

w1067-00038