

KOBE.

24th November, 1921.

W. Boylan

the Owners Representative survey the Steel Twin Screw Steamer "RAKUYO MARU", 9300 tons gross, of Yokohama on the 24th November 1921, as she lay afloat in this harbour to ascertain the nature and extent of damage to the Starboard L.P. Pinion flexible coupling sleeve, cause said unknown.

Upon examination of the sleeve the undersigned found two teeth slightly chipped and recommended that these two teeth be dressed up and the sleeve fitted back in position.

*W. Boylan*

Surveyor to Lloyd's Register.



© 2020

Lloyd's Register

W1067-0105 Foundation