

GROSS 1171
UNDER DK. 9464

Owners "ITALIA" Loc. Genoa, N. Italy
Masters

Owners' Address
(if not already recorded in Appendix to Register)
Port belonging to Genoa

3m, 11, 30.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME "VIRGILIO" Rpt. Gen. No. 16153

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The 1st Special Survey No. 3 due 4.40 has been partly held.

The Genoa Surveyors now report the vessel placed in dry dock and the Special Survey advanced.

A defective length of chain cable had been removed.

A bower anchor and a length of chain cable were lost.

A new bower anchor and 2 lengths of chain cable have now been supplied to replace the lost and removed equipment.

Some minor repairs have been effected and the bottom coated.

It is submitted the vessel appears worthy to remain as classed with record of survey 3.40 Gen.

100A1
With freeboard.
3.40 Gen.

S. L. Part held

12.4.40



© 2020

Lloyd's Register
Foundation

this survey, thus, for example:—.....to remain as classed in the Register Book under the name of the vessel, to remain as classed with record of survey, 1.38, or "to remain as classed and to have record of survey, 1.38, and the notations of ss No. 1-38."

This vessel is eligible, in my opinion, to remain as classed with free