

Sc. "N.T. Nielsen Alouso"

Hbg 275.

Not due 12.28 held repairs effected
account of wear & tear & damage due
to board propeller striking an obstruction,
ion and grounding.
new Boiler, not built under special
ay fitted.

submitted that
el is eligible for
CORD.

M.C. 7.28.

7.28.

Amend particulars as follows:-

2DB + 2SB. G.S. 378. N.S. 13137.

8cf. N.H.P. 690. N.S.B(S) 7828.

Delete +.

cluded that the new

new Boiler can be used

steam to the main engine but
this should be confirmed.

© 2019

Lloyd's Register
Foundation

23/8/28.

W107-0062