

Received from Chief Ship Surveyor 26 JUN 1924

Received by Chief Ship Surveyor

ESSEL'S NAME Stl. Sc. "SOUTHERN KING" Rpt. Rot. No13599

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

The Rotterdam Surveyors report this vessel placed in dry dock and the requirements of the 2nd.s.s.No.1 complied with.

The bottom has been cleaned and coated, 15 fathoms of chain cable verified with the certificates of test, two shell plates renewed and several shell plates and frames faired and minor repairs effected.

Some damage to deck plating, etc. through fire has been repaired as necessary.

Alterations have also been effected with a view to the vessel carrying whale oil and oil fuel in bulk as cargo, in accordance with approved plans and to the Surveyors' satisfaction.


It is submitted the vessel appears worthy to be classed 100A1 "Carrying whale oil or oil fuel in bulk F.P. above 150°F" with record of survey 6,24 and notation of s.s.Rot.No.1-24. Without special conditions.

100A1
6,24 Rot.) without, etc.
s.s.Rot.No.1-24.)

Carrying whale oil or oil fuel in bulk F.P. above 150°F.

[Handwritten signatures]
24.6.24.

Delete "Carrying oil fuel F.P. above 150°F. in pt. DB".



© 2020 Lloyd's Register Foundation

W1070-0176 1/2

See letter

It is concluded the stiffeners on the new bulkhead on frame No.132 are as approved but the Surveyors should be requested to state if this is so, and it should be pointed out to them that in future similar cases details of scantlings need not be reported provided the alterations are carried out in accordance with plans approved and such plans are forwarded with the report.

See 1/7/24.



74.6.74



© 2020

Lloyd's Register

W1070-0176 3/2 on