

DCW

Chief Ship Surveyor

Received from Chief Ship Surveyor

110 AUG 1948

SHIP NAME **WARREN GROVE**

REPORT **Nwc.**

No. 105427

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. —Extract from Sub-Committee's Report, 24/5/92.)

For conditions of class, see previous endorsement.

The NEWCASTLE Surveyors report the vessel afloat and 15 fathoms of chain cable, as above, supplied and verified with certificate.

IT IS SUBMITTED the vessel is worthy to remain as classed, subject to cement boxes in hold (s.s.) and fore peak being removed and necessary repairs carried out at the next dry docking, but without other condition.


As Now, Subject
 Without

J.M.B.
3/8/48.

INSERT IN S.R.L.:-

(Bottom forward is set up)

CARGO BATTENS NOT FITTED



© 2020

Lloyd's Register
Foundation

W1070-0256