

2 E

ed by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

21 MAY 1951

VESSEL'S NAME

"ACCLIVITY"

REPORT

Lon.

No. 122354

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/52.)

re of Survey COMPLETION OF SPECIAL SURVEY OF ENGINES AND BOILERS FOR S.S. - No.

This Survey, due 7.50 ~~17.50~~ partly held as a CS now completed, and the following repairs carried out (due to wear & tear):-

Minor repairs carried out.

It is submitted the vessel is eligible to remain as classed, with notation of LMC CS 4.51 as recommended.

Survey commenced 5.50.

DBS due 3.51.



© 2020

17. 5. 51.

Lloyd's Register
Foundation

W1071-0013