

ON ADMIRALTY, WAR OFFICE & INDIA OFFICE LISTS

THE PLENTY-STILL OIL ENGINES LIMITED

DIRECTORS
MAJOR C.H.L. GAZALET D.S.O.
E.P. PLENTY
H. KENT-NORRIS (MANAGING)

KING'S ROAD
NEWBURY
ENGLAND

TELEGRAMS & CABLES
ECONOMY-NEWBURY
CODES
A.B.C. & BENTLEY
PHONE: 528



YOUR REF

DATE

OUR REF

Spare Parts for Auxiliary Engine.

Engines ~~633~~ 633

Brown Prod. 182

- 1 fuel jet complete.
- 1 set of piston rings.
- 1 set of studs and nuts for cylinder head.
- 1 gudgeon pin.
- 2 bottom end bolts.
- 1 set of piston rings for compressor.
- 1 half set of suction & delivery valves for compressor.
- 1 complete set of working parts for fuel pumps.
- 1 set of valves for general service pump.
- 1 spare fuel pipe.
- 1 set of springs.
- 1 crankcase door leather.
- 1 top half cylinder head.



© 2020

Lloyd's Register
Foundation

W1071-0065

internal surfaces of the receivers be examined and cleaned

Yes.

Is a drain fitted at the lowest part of each receiver