



Lloyd's Register of Shipping,

Merchants' Exchange, Bute Street,

Cardiff, 12th. September 1924.

Dear Mr. Watt,

With reference to the Steamer "ROSALIE"
(ex COMPASS), a freeboard verification form has today been
forwarded to London for new certificates due to change of
name.

The freeboard stated on the present certificates
is $10\frac{1}{2}$ " and is so marked on the vessel's sides, but in the
Register Book the freeboard is given as 10".

I thought it advisable to let you know of
this small discrepancy before the new certificates are
issued in case it is the certificates that are in error.

Yours faithfully,

L. S. Ainsworth

W. Watt Esq.,

LONDON.



© 2021

Lloyd's Register
Foundation

W1073-0254