

REPORT OF SURVEY FOR REPAIRS, &c.

DISCLOSED
BAY No.

Date of writing Report.....

19.....

When handed in at Local Office.....

19.....

Port of

London

No. in
Reg. Book.

Survey held at

Date, First Survey

Last Survey

1911

34227

on the Wood, Iron or Steel

s.s.

"Talang Akar"

(No. of Visits.....)

TONNAGE :-

GROSS

2046

UNDER DK.

1569

NET

1108

Built at

Hawerton Hill on Tees

By whom

Turners S.B. Co. Ltd.

When

1926

MONTH

10

Owners

N.V. Ned. Koloniale Handels Maats. Owners' Address

(If not already recorded in Appendix to Register Book)

Managers

Port belonging to

Salem Karang

Surveyed Afloat or in Dry Dock?

Name of Dock

Destined Voyage

Cell D B D Ba

feet ; u E & B

feet ; f

feet

total capacity

tons. FPT

tons ; APT

tons ; MT

feet

tons.

Only alterations in the existing records of tanks should be inserted.

N.B. All alterations in the existing records should be underlined.

Last Report, No. 4460

Port Slat

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined.

Was a damage report made by anyone else? if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

CHARACTER.
* for Special Survey.
Date of last Survey and of
Periodical Surveys.Machinery and Boiler
Surveys
(Including date of N.B., if any)

+100A1

+LMC 938

941

BS 941

88 Eng No 3-938

TS CL 941

Carrying pet in bulk

Fitted for oil fuel, 10.26 above 150°F

NO LATER SURVEY REPORTED

Society's Freeboard (if assigned) as }
painted on Ship and now verified } ft. ins.

SUMMARY OF DAMAGE REPAIRS :-	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items :-
Renewed ...								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place ...								

PRESENT CONDITION OF THE

Decks	Bulkheads	Engine Room Skylights	Copper, or Y.M. (State if on Felt.)
Caulking of Decks	Ceiling	Coal Bunkers, Openings, Covers, &c.	When fitted, Month Year
Coamings	Cement or Asphalt	Oil Bunkers	Boats
Beams & Fastenings	Rudder	Scuppers	Masts, Yards, &c.
Outside Plating	Steering gear and its connections	Cargo Hatchways	Condition, how ascertained (State if wedges removed.)
" " in way of sidelights	Windlass	Hatches	Equipment letter
Frames	Have pumps been examined and found efficient?	Planking	Anchors, No. of
Reverse Frames	Have Sluice Valves been examined and found efficient?	Caulking	Cables (State if now ranged)
Longitudinals	Have Watertight Doors been examined and found efficient?	Treenails	" length mean diamr. (on board.)
Transverses	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson	" Rule length size
Floors	Air and Sounding Pipes	Transoms, Pointers & Crutches	Chain Locker
Keelsons	Doubling Plates under Sounding Pipes	Timbers of Frame at openings	Hawsers & Warps
Stringers		" " at other places	Standing and Running Rigging
Inner Bottom Plating		Stringers, Clamps & Shelves	Sails
Have the Tanks been examined internally?		Salting (State if examined.)	
Have the Tanks been tested?			

General Observations, Opinion as to Class, Recommendation, &c. :-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example :- "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

Survey Fee (per Section 29)	£	:	:	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 29)	£	:	:	19.
Travelling Expenses (if chargeable)	£	:	:	Received by me,
Second Surveyor's Fee (if any)	£	:	:	19.


Committee's Minute

TUES. 4 APR 1944

Character Assigned

OMIT CLASS
ON RE-PRINT.

Surveyor to Lloyd's Register of Shipping.



© 2020

Lloyd's Register
Foundation

W1075-0157