

3m, 11, 35

The class is subject to the boilers being repaired.

3E

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME "WAHINE"

Rpt. Wel

No. 2176

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/32.)

Nature of Survey SPECIAL SURVEY OF ENGINES AND/OR BOILERS PARTLY HELD FOR S.S. No. 3

LMC

LMC (M)

MS

BS

due 12,36 , partly held

~~now further advanced~~ and the following repairs effected (due to wear & tear.

One boiler renewed.

Tubes and headers of 4 boilers renewed and 2 boilers removed from the ship.

Funnels partly renewed.

Minor repairs to turbines, pumps etc.,

It is proposed to complete the survey at the next Annual Survey.

It is submitted that this proposal merits approval and the vessel is eligible to remain as classed, and WILL BE eligible for the record

LMC 12,36 when the survey has been completed. and BS 12,36 now.

without special condition

The following remains to be done to complete the Survey

Examine port LP turbine and shafting, ~~circulating and air pumps; also the port generator engine.~~

It is submitted the Surveyor be requested to forward a sketch showing the position of the boiler which has been entirely renewed, relative to the other boilers in the vessel. He should also furnish a sketch of the air receiver now fitted in connection with the tube cleaning plant. It is concluded that this receiver has been made and tested in accordance with the Society's Rules, but this should be confirmed.

for RB. Delete 8 WTB.  
Insert 6 WTB.

Amend HS to  
Amend NHP to

20173.  
1461



© 2019

Lloyd's Register  
Foundation

18.2.37.

W1076-0136