

any further communication should be
addressed to:—

THE SECRETARY
The address given opposite.
The following number should be
noted:—

M. 2548/50

Telegraphic Address:
(Shipping)
"SHIPMINDER, TELEX, LONDON."
(Inland Transport)
"TRANSMINRY, TELEX, LONDON."

Telephone No.: MAYFAIR 9494
Extn. 3464

reference

MARINE SAFETY DIVISION,
MINISTRY OF TRANSPORT,

BERKELEY SQUARE HOUSE,
LONDON, W.1.



24th October, 1950.

RECEIVED

25 OCT 1950

ANSD.....

Sir,

I am directed by the Minister of Transport to inform you
that the Formal Investigation ordered into the circumstances
attending the loss with all hands of the Milford motor trawler
"MILFORD VISCOUNT" O.N.165644, has been fixed for hearing at the
Town Hall, Milford, Pembrokeshire on Monday, 27th November, 1950,
to commence at 10.30 a.m.

I am, Sir,

Your obedient Servant,

The Secretary,
Lloyd's Register of Shipping,
41, Fenchurch Street,
E.C.3.



© 2021

Lloyd's Register
Foundation

Your obedient Servant,

CLASSIFICATION

Handwritten signature

W.L.

*82B
26.10.60*



© 2021

Lloyd's Register
Foundation

*82B
W.L.*

FORWARD V
or and
sent the
delay S
Find
I endd
official
mon th
Further con
to: -
THE SER
Address given
following
No. 25
Telephone
LINDER
(Inland
SMINRY,
Telephone No. 4
R 9491
reference.....
Sir,
I
you th
circum
Milfor
This t
fishin
seen s
A
the da