

...ificate N. 47802 and is of the  
...ion this anchor was not placed on

Further communication should be  
to: —  
**THE SECRETARY.**  
Address given opposite.  
Following number should be  
M. 2548/50.

---

Telegraphic Address:  
(Shipping)  
INDER, TELEX, LONDON."  
(Inland Transport)  
SMINRY, TELEX, LONDON."

---

Telephone No. **ABBEY 7711**  
r 9491, Extn.  
Reference.....

MARINE SAFETY DIVISION,  
MINISTRY OF TRANSPORT,

BERKELEY SQUARE HOUSE,  
LONDON, W. 1



12th July, 1950.

**RECEIVED**

15 JUL 1950

**ANSD**

Sir,

I am directed by the Minister of Transport to inform you that a Formal Investigation has been ordered into the circumstances attending the loss with all hands of the Milford motor trawler "MILFORD VISCOUNT", O.N.165644. This trawler left Castletown, Berehaven, for the Porcupine fishing grounds on the 30th March last, and has not been seen since the 1st April.

A further communication will be addressed to you when the date and place of hearing have been fixed.

I am, Sir,

Your obedient Servant,

Secretary,  
Lloyd's Register of Shipping,  
71 Fenchurch Street,  
E. C. 3.

© 2021

Lloyd's Register  
Foundation

W1078-0007



CLASSIFICATION

Referred to the Chief ~~Engineer~~ Surveyor  
and the Chief Ship ~~Surveyor~~.

Referred to Mr. ~~Cook~~.

R.S.

Handwritten notes and signatures, including "R.S." and "17.7.5".



© 2021

Lloyd's Register  
Foundation