

Lloyd's Register of Shipping.

(Report on Vessel No. 54286.

Port

Hull

No.

SHIP FORGINGS OR CASTINGS.

I have to report that the undermentioned ~~Iron or Steel Forgings or~~
Castings, manufactured by Messrs. Bond's Foundry Co.
of Low Law, for the Vessel No. 1319, being built
by Messrs. Crompton & Sons Ltd. of Selby,
have been inspected by me as set forth below and found to be, so far as can
be seen, sound

Despatched to Messrs. Donkin & Co. Ltd.

Wallinggate

Mark on Forgings or Castings.

Lloyd's

No. 6873

A.E.G. 1.3.46

A.E. Galloway

1 TILLER AND TRUNION.

Sunderland.

	STERN FRAME.	RUDDER FRAME.	STEM.
Material	Concrete steel		
How made	Cast		
If annealed	Heat treated		
Dimensions	As per pattern		
Progress on Inspection	Thoroughly done		
Date when Inspected	26.2.46 to 1.3.46		
CASTINGS.			
Tests on Standard Test Pieces.	Test No. 284		
Tensile Test—			
Ultimate Tensile.	28.8		
Tons per sq. in....			
Yield Point.			
Tons per sq. in....			
Extension per cent.	33		
on.....2.....inches			
Red. of Area %			
Cold Bending Test—	120°		
Angle before fracture			
Drop Test—			
Height from ground ...			
Hammering Test—	Yes.		
If made according to Rules and found satisfactory ...			

SKETCHES OF FRAMES SHOWING POSITION AND DESCRIPTION OF WELDS OF FORGINGS.

Fee (if any chargeable) £ MONTHLY: A/C

To be paid at

* If of Iron, state whether scrap or puddled Iron. If of Steel, state whether made on the Open Hearth process.