

Lloyd's Register of British & Foreign Shipping,

97 & 98, Scottish Provident Buildings,
Donegall Square, West,

Belfast, 3rd Feb 1914



The Secretary,
London.

Sir,

I beg to acknowledge the receipt of your letter of yesterday's date having reference to the First Entry Report of the S.S. "Orlana" and with regard thereto beg to state that the thickness of the collision bulkhead at the foot should be .46 instead of .42 as reported. I regret this item was incorrectly reported.

I am, Sir,

Your Obedient Servant.

C. D. Kendall.



© 2021

Lloyd's Register
Foundation

gates on upper edge

spacing

30 1/2

30 1/2

Deck, Material and thickness Steel
Forecastle Deck Stringer Plate, b'dth & th'kns

Referred to the Chief Ship Surveyor,

Edw

M
4.2.14



© 2021

Lloyd's Register
Foundation