

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

21 JUL 1950

GB
VESSEL'S NAME 'J A L A M O H A N' REPORT Bon. No. 9481

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The BOMBAY Surveyors report (2.50), the vessel afloat and the Periodical Special Survey (D) due 4.50 commenced by the examination of holds, 'tween decks, No.3. D.B. tank and No.4. D.B. tank (s.s.).

The internal structure of the holds and 'tween decks was found in so bad a condition that the Owners decided that it would not be economical to effect repairs.

The Surveyors state the vessel is laid up and is to be sold for breaking up.

IT IS SUBMITTED a Notation of "To be broken up" be inserted in the Register Book.

INSERT IN R.B.

"To be broken up"



© 2020

Lloyd's Register
Foundation