


DETAIL OF RIVETING

MANHOLE COMPENSATION PLATE

PLATE % AT LONGITUDINAL EDGE = 85%

Nº. 472



Lloyd's Register
Foundation

W1086-0208